



State of New Jersey

DEPARTMENT OF ENVIRONMENTAL PROTECTION
WATERSHED AND LAND MANAGEMENT

DIVISION OF RESILIENCE ENGINEERING AND CONSTRUCTION
OFFICE OF DAM SAFETY & FLOOD ENGINEERING

44 S. Clinton Avenue, 3rd Fl.

P.O. Box 420, Mail Code 44-03A

Trenton, New Jersey 08625-0420

Tel. (609) 984-0859 • Fax (609) 984-1908

<http://www.nj.gov/dep/damsafety>

PHILIP D. MURPHY
Governor

SHEILA Y. OLIVER
Lt. Governor

SHAWN M. LATOURETTE
Commissioner

June 8, 2023

Mr. David Mazzella
President, Seneca Lake Club, Inc.
P.O. Box 505
Sparta, NJ 07871

Re: Dam Safety Inspection Report for Seneca Lake Dam
NJ Dam File No. 22-183
Sparta Township, Sussex County

Dear Mr. Mazzella:

This letter acknowledges receipt of a report for the 2022 regular dam safety inspection for the referenced dam submitted as required by the New Jersey Dam Safety Standards, N.J.A.C. 7:20-1.11.

The Bureau of Dam Safety (Bureau) reviewed the report and the structure was found by your engineer to be in **Satisfactory** condition. You must proceed to implement the recommendations of your engineer in accordance with the report and Compliance Schedule. Recommended maintenance/repair work such as grass mowing, brush and debris removal, minor concrete repairs, minor erosion repairs, gate maintenance, etc. may be undertaken without further approval by this office. The Bureau must approve any repairs that are not considered general maintenance. Please also be reminded that your dam's next inspection is due two years from the date of this current report.

For further information regarding New Jersey Dam Safety, including copies of the New Jersey Dam Safety Standards and applicable forms, please refer to the Dam Safety web page at <http://www.nj.gov/dep/damsafety>.

Should you have any questions, please contact Zachary Kohl of this office at (609) 984-0859 or via e-mail at Zachary.Kohl@dep.nj.gov.

Sincerely,

Clint J. Oman, P.E., Manager
Bureau of Dam Safety

c: Sparta Engineer & Clerk
Sussex County Engineer
Jessica Bergmann, P.E., GZA GeoEnvironmental, Inc.

V:\nhr\bdscf\DSS\DATABASE\23\letter\22183ZEK23a.docx