



Known for excellence.  
Built on trust.

GEOTECHNICAL  
ENVIRONMENTAL  
ECOLOGICAL  
WATER  
CONSTRUCTION  
MANAGEMENT

55 Lane Road  
Suite 407  
Fairfield, NJ 07004  
T: 973-774-3300  
F: 973-774-3350  
www.gza.com



February 6, 2025  
12.0076755.03

Mr. Clint Oman, P.E., Bureau Chief  
NJDEP Division of Resilience Engineering and Construction  
Bureau of Dam Safety  
501 E. State Street, 1<sup>st</sup> Fl.  
PO Box 420, Mail Code 501-01A  
Trenton, NJ 08625-0420

Re: Transmittal of 2024 Regular Inspection Report  
Seneca Lake Dam (NJDEP File No. 22-183)  
Sparta Township, Sussex County, New Jersey

Dear Mr. Oman:

GZA GeoEnvironmental, Inc. is pleased to submit the 2024 Regular Inspection Report and Compliance Schedule for Seneca Lake Dam on behalf of Seneca Lake Club.

The dam was found to be in "satisfactory" condition. Specific findings and recommendations are contained within the report.

Thank you and please contact us with any questions or if you require any additional information.

Sincerely,  
GZA GEOENVIRONMENTAL, INC.

Jessica Bergmann, P.E.  
Senior Project Manager

Christopher S. Adams, P.E.  
Principal/Senior Vice President

cc: Seneca Lake Club, Inc.